ChengYing

CYS Infrared Multi-Touch Overlay

2   Installation Instructions

Video link of the installation: https://www.cynnn.com/?p=679

2-1 Item list: Infrared Touch Frame, User manual, Screw x 8, Screwdriver, Double-sided adhesive tape.


Unpack. After taking out all the items, please make sure the product is in good condition. If there are frame deformation, Corner or data line damage, missing items, please take pictures and save in time, don't carry on the next operation again. And then contact us. (Refer to title 4)

2-2 Show the side with colored letter upwards. Take all parts of the frame and place them on the corner which pastes letter with the same color.

2-3 Connect the frame section on each side with plug in.

## 2-4 Use screws to fix the touch section on each side.

2-5 Flip over to the front of the product, connect the USB of it to a computer and test the touch function.

2-6 Once the test is successful, paste the double-sided adhesive tape on the back of the touch frame.   For products over 55 inches, more double-sided tape is required.

2-7 Mount the touch frame to your monitor with double-sided adhesive tape.

2-8 Connect the touch frame USB cable to your computer.

Monitor

PC

IR Touch Frame

HDMI/VGA cable

USB cable

Side View

Contact Support Team for more information:
Email address: supports@cynnn.com; info@cynnn.com
www.cynnn.com